CONFINENTIAL CONFIDENTIAL CLASSIFICATION 50X1-HUM REPOR CENTRAL INTELLIGENCE AGENCY IN TORMATION FROM FOREIGN DOCUMENTS OR RADIO BROADCASTS CD NO. DATE OF 1945 INFORMATION COUNTRY Scientific - Metals, oxidation DATE DIST. 28 Sep 1951 **SUBJECT** HOW Book **PUBLISHED** NO. OF PAGES 4 WHERE Sverdlovsk/Moscow **PUBLISHED** DATE 1945 SUPPLEMENT TO **PUBLISHED** REPORT NO. Russian LANGUAGE THIS IS UNEVALUATED INFORMATION

SOURCE

STATE

Γ

Okisleniye metallov pri vysokikh temperaturakh, Metallurgizdat, 177 pp,

50X1-HUM

# TABLE OF CONTENTS OF THE BOOK, "OXIDATION OF METALS AT HIGH TEMPERATURES"

V. I. Arkharov

	Page
ntroduction. Subject and Scope of Investigation	
1. Significance of Investigating the Oxidation Process in	3 4 5
2. Two Directions in Studying the Transport	5
2. Two Directions in Sound the Phenomenon 3. Diffusion Character of the Phenomenon 4. Effect Produced by the Conditions of Contact of a Scale 4. Effect Produced by the Pate of Process	7
With Adjacent Media on the Resonant Medium for Significance of the Scale as an Intermediate Medium for	8 8
the Rate of Process	0
7. Limitation of the Field that the Oxidation Process	9
8. Elements Which Determine the Bulletin	9
Process 9. Dual Significance of the Structural Characteristics of	11 12
Scale  10. Experimental Means and Methods for Investigation  11. Specific Difficulties of Investigating the Structure of	17
Scale	-1
Chapter I. Preliminary Review of Oxide Phases Which Occur in a	
Study of Scale	20
1. Classification of Oxide Phases	21. 24
2. Basic Phases	24

CONFIDENTIAL

-1-

## CONFIDENTIAL

٢

#### CONFIDENTIAL

50X1-HUM

<u> </u>	age
a Tun and Other Notels With Exact	
4. Complex Oxides of Iron and Other Metals With Exact	24
Stechiometric Composition  Stechiometric Composition  Complex Oxides of Iron and Other Metals Without Exact  Complex Oxides of Iron and Other Metals Without Exact	26
Charbiometric Composition (Solid Solutions)	26 26
Crustal Tattices of Oxide Phases	20 34
. a tallogramme of Oxide Phase	36
	50
9. Phase Diagram of the Iron-oxygen by Steel Oxi- This Diagram for Investigating the Process of Steel Oxi-	36
dation	_
Chapter II. General Characteristic of the Structure of Scale	
1. Division of Metals into Two Types According to the Structure	
of Their Scale (Pilling-Bedworth Criterion)	39
the scale of the scale of the scale of	40
of the Scale Of Utilet Medical	fift fift
Z	44 45
	47
<ol> <li>Microstructures of Iron Scale</li> <li>Phase Composition of Scale According to Data of X-Ray</li> </ol>	47
Analysis - (First Approximation)	48
7. Mechanism of the Oxidation Process (First Approximation)	
Chapter III. Structure of the Oxide Films on Metals at Initial	
Chapter III. Structure of the Oxide Films on Mc.5525 as Stage of Oxidation	
1. Significance of the Initial Stage of Oxidation for Clari-	53
fying the Mechanism of Process	/3
2 Y-Ray Threstigation of the Early Stages of the officer	54
	•
Process of Iron and Steel  3. Limitation of Possibilities for the Method of X-Ray	59
Analysis of Thin Films	60
4. Structure of the Primary Oxide Film on Iron 5. Structure of Oxide Films at the Initial Stage of Oxidation	/-
at Elevated Temperatures	65
at Elevated Temperatures  6. Protective Nature of the Phases With Spinal-Type Lattice	66
Chapter IV. Quantitative Regularities in the Oxidation Process of	
Metals	
1. Quantitative Relations Among Various Factors of the Oxidation	68
Process as an Image of the Process as the Whickness of Scale	69
<ol> <li>Parabolic Time Law of Increase in the Thickness of</li> <li>Exponential Temperature Law of Increase in the Thickness of</li> </ol>	
3. Exponential Temperature Law of International	70
Scale 4. Significance of the Electrical Conductivity of Oxide Phases	70
for Studying the Mechanism of Oxidation	72 75
	78
C d demont a Whoory	10
6. Smirnov's incorp	a
Chapter V. Correlation Between the Structure of Scale and the Oxidation	-
Rate of Iron and Steel at high remains	
1. Relation Between the Structure of Scale and the Oxidation Rate	
1. Relation Between the Structure of Scale and the California	82
of Iron	
	84 86
tite in Scale and the Intensification of Principles of Steels 3. Hypothesis on the Mechanism of the Heat Resistance of Steels	00
4 TADOCTICATO OT ATT	

- 2 -

#### CONFIDENTIAL

CONFIDENTIAL

### CONFIDENTIAL

CONFIDENTIAL

٢

50X1-HUM

·	Page
4. Experimental Verification of the Hypothesis on the Heat-	86
Resistance Mechanism Variations on the Heat-Resistance	90
Mechanism by the Reducts Deposits of Chromium and Nickel	95
on the Oxidizability of From Between the Structure of	95
7. Attempts to Establish of Copper Scale and the Oxidation Rate of Copper Scale and the Oxidation Rate of Copper 8. X-Ray Investigation of the Phase Composition of Cobalt	96
Scale  Chapter VI. Nature of Wuestite and Its Significance for the Oxidation	ι
Chapter VI. Nature of Wuestite and Its Significants Process of Iron and Steel	
1. Composition and Structure of Wuestite	97 106
2. Phases CoO and NIO 2. Practision X-Ray Investigation of Phases FeO, CoO, and NIO	107
in Scale .  in Scale .  Differences in the Nature of FeO Phase and CoO and NiO Phase  4. Differences in the Nature of Oxidation of Iron, Cobalt, and Nick and Diverse Character of Oxidation of Iron,	s el 108
Neture of the Gamma-Fe <sub>2</sub> 0 <sub>3</sub> Phase	
1. Intermediate Stage in the Process of Conversion (Oxidation)	114 115
2. Structure of the Gamma-Fe <sub>2</sub> O <sub>3</sub> Phase in the Oxidation Proce	ess 120
of Iron and Steel  Orientation Relations Between the Crystal Lattices of Metals and Oxide Phases During Oxidation	
courtelline Surfaces	121
o Orienting influence of the day	123 1
Gas Adsorption Gas Ad	124
h Orientation Relations between one	126
Oxides 5. Orientation Relations Between the Lattices of Other Metals	132 134
and Their Oxides 6. Regularities Controlling the Orientation Relations 7. Significance of Orientation Relations for the Oxidation	13 <sup>l</sup> +
7. Significance of Offendorsh and Process of Metals	25.
Chapter IX. Texture in Scale	106
onep est	136 ±37
2. Two Kinds of Radial Textures in Scale	138 140
3. Presence of Radial Textures in Scale 4. Texture in the Exterior Layer of Iron Scale	141
c moveture in the Middle Layer Cools	144
6. Texture in the interior harden of the Oxidation Proce	ss 145
7. Detailing the Structural Mechanism of Iron Scale of Iron on the Basis of Studying Textures in Scale 8. Texture in Iron Scale Formed During Oxidation of Iron in	147
Water Vapor	150
Water Vapor  9. Textures in the Scale of Cobalt and Nickel  10. Investigation of Texture in the Scale of Chromium	153

- 3 **-**

CONFIDENTIAL

CONFIDENTIAL

٢

# CONFIDENTIAL

50X1-HUM

•	Page
Chapter X. Structural Picture of the High-Temperature Oxidation Process of Iron, Low-Carbon Steel, and Certain Other Metals	
1. Three Stages of the Oxidation Process of Iron and Steel	155
1. Three Stages of the Oxidation receiving Oxidation of Iron 2. Mechanism of Growth of Scale Layers During Oxidation	157
2. Mechanism of Growth of Scale Layers the Process of Oxidation	159
2. Mechanism of Reactive Diffusion in the Process of Oxidation 3. Mechanism of Reactive Diffusion in the Process of Oxidation	•
4. Peculiarities of the Oxidation Process of Nickel, Cobalt, and	163
<b>61</b>	443
5. Effect of Alloying Elements on the Oxidation Process of Iron.	163
not at the West-Registance of Steel	
6. Methods of Developing the Composition of Heat-Resistant Alloys	105
o. Methods of Development	
	166
Bibliography	

- E N D -

CONFIDENTIAL

CONFIGERTIAL